

# Part Number Update

Bulletin No: PNU-152-000

Effective Date: June 28, 2010

Cancels: N/A

Page: 1 of 1

Subject: **Bendix® Actuator, Brake Chamber, and Rotochamber Part Number Obsolescence**

Bendix is committed to providing the industrial use and heavy-duty markets the best-in-class actuators. To keep our product offering in tune with demands of the market place, beginning September 1, 2010, the following Bendix® service parts will no longer be available.

Brake Chambers		
Description: Type Number	Part Number	Recommended Alternate(s)*
TYPE-3	289279	282047, 104259N
TYPE-6	285818N	N/A: Family Obsolete
	278638N	
	282973N	
	228908N	
	227589N	
	225152	
	227589	
	282973	
	278638	
	228908	
	285818	
	229770	
	275949	
	284751	
TYPE-9	226694N	279558N
	227550N	
	228909	
	276800	
TYPE-12	226051	287740
TYPE-20	225925	109763N
	229300	
TYPE-36	228915	288820
	288819	

AH-1 Air-over-Hydraulic Actuator		
Description: Type Number	Part Number	Recommended Alternate(s)*
AH-1	276251	N/A: Family Obsolete
	286408	
	286409	

Rotochambers		
Description: Type Number	Part Number	Recommended Alternate(s)*
TYPE-9	223186	222227N, 229814N
	223369N	
	223859N	
	226826	
TYPE-12	229042	229815, 288838N
	276171	
TYPE-20	108342	229817N
TYPE-24	222792N	101260N, 229818N
	281276	
TYPE-36	223719	226746, 229820N
	281280	
TYPE-50	226290	226747N, 229821N
	5000811	

**Please review your requirements and inventory. Make any final orders for these parts by August 31, 2010.**

\* The recommended alternate part numbers are the Bendix recommended potential replacements. Please review your application to determine if the alternate is suitable.

Other replacement options may be available. Call 1-800-AIR-BRAKE (1-800-247-2725) to speak with the Bendix Tech Team. Representatives are available to assist you Monday through Friday, 8:00 A.M. to 6:00 P.M. EST.



Bendix® brand foundation brake products are brought to you by:

**Bendix Spicer  
Foundation Brake LLC**  
A Bendix CVS and Dana Joint Venture